

0022Z 26 APR 64

SECRET

TO : DIRECTOR

25X1A

FROM :

ACTION: OPS 1-8

INFO :

ROUTINE

TO: 0326Z 26 APR 64

IN 75317

25X1A

25X1A

25X1A

25X1A

25X1A

TO

PRIORITY

INFO

CITE

A. S214A

B. B/08 09/10237

C. HTA/3B/D-19/1°45"/78 DEGREES

D. 1.93/1.80

E. 8402/247-5-12-11-3/9R/247-7-12-11-3/9L

F. (1) DRY

(2) GOOD

(3) FAIR (EXCESSIVE)

(4) GOOD

(5) GOOD

(6) POOR (REMARKS)

(7) OPERATING

25X1A

25X1A


G. [] RECEIVED AT 25/205Z APR IN COVERED STEEL BOXES.

[] WAS NOT RECEIVED. EXTENSIVE METERING PROBLEM NOTED ON 9R. THIS ERRATIC METERING BETWEEN FRAMES VARIES FROM TWO INCHES TO FOURTEEN INCHES. 9R RAN OUT AT EXPOSURE 2722. 9L CONTINUED TO 2829. FRAMES 55, 56, AND 72, 73 9R AND 9L WERE COMPLETELY

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

25X1A




(IN 75317)

S E C R E T

PAGE TWO

25X1A

OVEREXPOSED. INDICATIONS ARE THAT  METERED AT TIME OF FULL SHUTTER OPENING RESULTING IN A COMPLETE EXPOSURE WIPE WITH NO DISCERNIBLE IMAGE. ONE INCH MARKS EXTENDING INTO IMAGE AREA FROM DATA CHAMBER CONTINUED THROUGHOUT ENTIRE RIGHT SIDE. FILM ON 9R ALSO HAS INTERMITTENT DARK STREAK ALONG CENTERLINE OF FRAMES. THIS APPEARS TO BE SOME TYPE OF PRESSURE MARK. MARKS DO NOT SERIOUSLY DETRACT FROM IMAGE. NUMEROUS CRESENT SHAPED FOGGED AREAS ONE SIXTEENTH INCH WIDE TO ONE AND ONE-HALF INCHES LONG APPEAR INTERMITTENTLY ALONG TITLE EDGE OF 9R. METERING MALFUNCTION ON 9R WILL CAUSE DUPING PROBLEMS DUE TO EXCESSIVE LENGTH OF 9R PART, I.E., EACH BREAKDOWN OF 9R WILL BE APPROXIMATELY 260 TO 300 FEET LONG BECAUSE ODR LARGE SPACING BETWEEN FRAMES. ALL DUPING STOCK ON HAND IS IN 225 FOOT LENGTHS. HOWEVER, PAIR INTEGRITY HAS BEEN MAINTAINED AND ALL DUPES WILL BE SHIPPED IN 133 FRAMES PARTS. FILM FROM 9L SIDE APPEARS NORMAL WITH ONLY WIPE MALFUNCTION MENTIONED ABOVE. FRAME 0045R SUFFERED ONE-HALF INCH CUT DURING BREAKDOWN AFTER PROCESSING AS DID FRAME 2892R A TWO INCH CUT. OCCASIONAL SMALL EMULSION DEFECTS IN 1631, 1635, AND 2061, ALL 9R. TWO AND ONE-FOURTH INCH SCRATCH FRAME 1630L. FACTORY SPLICE ON 1041R AND 1672L.

END OF MESSAGE

S E C R E T